

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


A  
X-7

**History of original corner establishment:**

Corner established by Alonzo Gesner under GLO contract No. 683 and dated June 7, 1898.

Surveyor General records state: Set hemlock post 4' long 4" square 24" in ground for 1/4 Sec Cor marked 1/4 on the N side from which:

A hemlock 8" dia brs N11°E, 23 lks dist mkd 1/4S BT.  
A fir 8" dia brs S65°E, 18 lks dist mkd 1/4S BT.



**Description of corner evidence found:**

No trace of original wood post.

A hemlock 14" dia brs N03°E(record, N11°E), 15.2' with healed blaze.  
A fir windblow snag 8" dia & root hole brs S88°E(record, S65°E), 11.9' dist with fragmentary scribes on rotten blaze.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>8-12-87</u>
Date Filed	<u>8-24-87</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>61-87 R</u>

**Description of monument and accessories established to perpetuate the original location of this corner:**

At position determined by distance intersection from recovered original BT remains...

Set 2½" aluminum cap on 2" aluminum pipe 25" in ground with 5" projecting out of ground with surrounding earth mound and 6' fence post alongside with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

A hemlock 8" dia brs S79°E, 26.2' dist mkd 1/4S5 BT.

Compass declination 17° East.

I hereby certify that the above described corner monument was properly remonumented by me and witnessed by Jim DeMastus on July 17, 1987.

*Jim DeMastus*

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*William L. Hanley*

**OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639**

Office of..... County Surveyor..... County of..... Union.....  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....

(COUNTY OFFICIAL)

(DEPUTY)