

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


J-11

History of original corner establishment:

Corner established by John W. Campbell, under Contract No. 429, dated March 10, 1884, page 80 of the Government Field Notes for T 4N R 39E.

N 89°47' W true line between Secs. 9 and 16
39.70' Set tamarack post 3' long 3" square 24" in ground.

A spruce 18" in diam. bears N 5° W 18 lks.
A tamarack 11" in diam. bears S 18° W 7 lks.




No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

I was unable to find any scribing at the described position as noted by J. W. Blom in 1972. No evidence of the 3" post was found at the described location. Because of the lack of evidence, I consider this to be a lost corner, and no monument was set.

Description of monument and accessories established to perpetuate the original location of this corner

NONE



Office of.....County.....Surveyor..... County of.....Union.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the day of

..... by

(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 11-83 R

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

James H. Buisson

OREGON BOARD OF
 SURVEYORS
 JULY 22, 1977
 JAMES H. BUISSON
 1001

CERTIFIED RECORD OF LAND COR

UMENTATION

History of original corner establishment:


Corner established in 1884 by Frank W. Campbell under General Land Office contract number 498. Surveyor General record states:

Set a tamarack post 3 feet long, 3 inches square, 24 inches in the ground for 1/4 section corner, marked 1/4 S on the North face.

From Which:

A spruce 18 inches in diameter bears N 5° W, 18 lks. marked 1/4 S BT.

A Tamarack 11 inches in diameter bears S 18° W, 7 lks. marked 1/4 S BT.



No record of subsequent monumentation found in County Records. Description of corner evidence found:

NONE


See map of survey dated July 1985, filed with Union County Surveyor. Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate position I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 27 inches in the ground.

From Which:

A 14 inch Larch bears N 78° E, 16.5 feet, marked 1/4 S 9 BT. on a single blaze.

A 14 inch White Fir bears S 6° W, 7.7 feet, marked 1/4 S 16 BT. , on a single blaze.



I set a steel fence post 5 feet East with a 54-2 and 54-4 sign attached. I also set a steel fence post 5 feet West with a 54-2 sign attached.

Corner set July 9, 1985

Witness: Rick Robinson, Stratton French

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gregory T. Blackman

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to center of new B.T.s

OREGON
Office of
GREGORY T. BLACKMAN
Surveyor

..... County of.....
I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 8-7-85 880-788-275

Date Filed 8-7-85

By G. LANGLITZ, DEPUTY

File No. 44-85 R