


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not previously set.



Description of corner evidence found:

Not previously set.

UNION COUNTY SURVEYOR

Date Received 10-2-86

Date Filed 10-13-86


By G. LANGLITZ DEPUTY

File No. 156-86 R

SEE SURVEY 35-86

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2' x 30" galvanized iron pipe with 2 1/2" brass cap marked: Pipe is set into ground 6" in a mound of stone. A steel fence post is set 5' from the brass cap with a USFS Land Survey Monument sign attached.



Bearing Trees:

A 13" Ponderosa Pine bears S86°30'W, 319.1' scribed N 1/16 S12 BT in a single blaze. A 12" Ponderosa Pine bears S34°30'W, 378.1' scribed N 1/16 S12 BT in a single blaze. A 3/4" aluminum awsher stamped RLS 852 is nailed between the letters B and T on each tree. A 6" red band is painted around each tree and USFS Bearing Tree and Land Survey Monument signs attached.

I certify the above corner point was established as hereon described on September 6, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR

David L. Haddock

**OREGON
JULY 12, 1968
DAVID L. HADDOCK
852**

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)