


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established by Rufus S. Moore under General Land office contract no. 451, dated June 12, 1882. Surveyor General Records states: Set a Basalt stone 16"x13"x8", 11 inches in the ground for 1/4 section corner marked 1/4 on North face and raised a mound of stone alongside. Pits impracticable



No record of subsequent remonumentation was found in County Records.  
Description of corner evidence found:

Found stone 16"x13"x8", well marked with a small mound of stone along west side.

**UNION COUNTY SURVEYOR**  
Date Received 12-5-85  
Date Filed 12-6-85  
By G. LANGRISH, DEPUTY  
File No. 129-85 R

See map of survey dated November 1985.


Description of monument and accessories I established to perpetuate the original location of this corner: In place of stone, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 28" in the ground with surrounding mound of stone from which:

A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker Bears N32°W 18.93 feet, ( Next to post in fence line )

A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker Bears S47°W 13.98 feet, ( next to post in fence line )

Buried original stone north.  
Set a steel fence post approximately 5 feet north with 54-4 sign attached.

Corner set 10/6/85  
No witnesses.



**REGISTERED PROFESSIONAL LAND SURVEYOR**

OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

Brass washer nailed to BT blaze.  
Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)