


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None

UNION COUNTY SURVEYOR

Date Received 12-5-85

Date Filed 12-6-85

By G. LANGLITZ, DEPUTY

File No. 156-85 R

See map of survey dated November 1985.

Description of monument and accessories established to perpetuate the

original location of this corner: At position determined by survey I set a 2 1/2" x 30" aluminum pipe with aluminum cap marked as shown, 30 inches in the ground with surrounding mound of stone, from which:


A 5/8" x 30" iron pin with plastic cap marked BGA Survey marker bears N29°E, 9.27 feet.

A rock outcrop 9 feet by 6 feet by 2 feet bears S25°E, 24.27 feet, marked + B0 on Northeast Corner.

Set steel fence post approximately 5 feet North with 54-9 sign attached.

Corner set 10/17/85

Witness: Rick Robinson, Stratton French



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)