


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. J-2

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap stamped:

Set pipe 18" in ground with mound of stone to cap.

From which:

A Doug. Fir 13" dia. bears S35°E, 13.9 ft. scribed W 1/16 S 18BT.

A Pond. Pine 12" dia. bears N23°E, 68.0 ft scribed W 1/16 S 7 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washers stamped LS 1099 to foot blaze of both BT's.

Painted blazes & 6" band around both BT's red. Attached 54-2 & 54-9 signs to metal fencepost set 5' West of corner & 54-2 sign to metal fencepost 5' S of corner.

Corner falls on slight N. slope at N. End of a small clearing approx. 200' West of new logging road.

Compass declination: 18° 15' East

Witnesses: Rodger Orton

Mike Wagoner

I hereby certify that the above described corner and/or accessories was established on Oct. 16, 1980

T4S R36E  
W 1/16 S 7  
S 18  
PLS 1099  
1980

Office of Union County Surveyor County of Union  
State of Oregon, I hereby certify that the within Instrument was filed in this office  
for record on the \_\_\_\_\_ day of \_\_\_\_\_  
\_\_\_\_\_ by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gary L. Langlitz*  
OREGON  
JULY 22, 1977  
GARY L. LANGLITZ  
1099

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 469-84R