

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

Index File No. L-1


**History of original corner establishment:**

Record of the original survey by Jacob Cooper, contract No. 397, 1881, states:

Set post 3 ft. long, 3 ins. square, 18 ins. in the ground on NW slope in open Pine timber, 50 ft. above bottom of ravine, for 1/4 sec. cor. marked 1/4S on East and West faces;

A Pine, 12 in. diam. bears S21°W 13 lks. dist., marked 1/4S BT.

A Pine, 30 in. diam. bears S43°E 79 lks. dist., marked 1/4S BT.



**Description of corner evidence found:**

None

**Description of monument and accessories I established to perpetuate the original location of this corner**


At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:

Set pipe 22" in ground with mound of stone to cap

From which:

A Douglas Fir 15" dia. bears S80° 30'W 14.5 ft scribed: 1/4S 13 BT

A Ponderosa Pine 8" diam. bears S22°E 54.6 ft scribed: 1/4S 18BT



Attached 54-3 & 54-4 signs to both BT's. Attached brass washers stamped LS 1099 to foot blaze of both BT's.

Painted blazes & 6" band around both BT's red. Attached 54-4 sign to metal fencepost set 5' North of corner.

Corner falls on N-W slope at North end of long clearing. Approx. 360' North of U.S.F.S. Road No. S410.

Compass Declination: 18° East

Witnesses: Rodger Orton

Mike Wagoner

I hereby certify that the above described corner and/or accessories was established on Oct. 16, 1980.

Office of \_\_\_\_\_ County Surveyor

County of \_\_\_\_\_ Union

State of \_\_\_\_\_ Oregon

I hereby certify that the within Instrument was filed in this office for record on the \_\_\_\_\_ day of \_\_\_\_\_

(COUNTY OFFICIAL)

by \_\_\_\_\_

(DEPUTY)

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Gary L. Langlitz*  
**OREGON**  
JULY 22, 1977  
**GARY L. LANGLITZ**  
1099

**UNION COUNTY  
SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 472-84R