


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. M-2

History of original corner establishment:

Not established during original survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2 1/2"x30" Galvanized Pipe with brass cap stamped:

Set pipe 14" in ground to rock with mound of stone to cap.

New BTs:

A Ponderosa Pine 10" dia. bears N3°W 35.7 ft., scribed SW 1/16 S18 BT.

A Ponderosa Pine 9" dia. bears S62°W 42.2 ft., scribed SW 1/16 S18 BT.

Attached 54-2 and 54-9 signs to metal post 5' north and 54-2 sign to metal post 5' east of corner.

Attached 54-3 and 54-9 signs to both BTs. Attached brass washer stamped LS 1099 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red.

Corner falls on east slope in long narrow NW-SE clearing approximately 250' east of USFS Road.

Compass Declination:

18° 15' East.

I hereby certify that the above described corner and/or accessories was established on October 20, 1980.

Witnesses: Rodger Orton
Alan Hanley

T4S R36E
SW 1/16 S18
PLS + 1099
1980

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary L. Langlitz

OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Due Filed _____

By _____

File No. 476-84R