


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Not an original GLO corner.

Index File No. R-20



Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.
Set 2.5"x30" aluminum capped aluminum pipe rising 10" above ground. Set steel fence post 3.5 ft. south of corner.

T5S R35E
E1/16 $\frac{S\ 23}{S\ 26}$
RLS 1844
1985

New BT's:

- 10.5" P. Pine bears N25.5°E, 67.5 ft., blazed and scribed: E 1/16 S23 BT.
- 6.5" P. Pine bears S4°W, 38.5 ft., blazed and scribed: E 1/16 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is 125 ft. north of road 5100-257, 96.0 ft. west and 14.0 ft. south of fence corner.

Compass Declination: 19 1/2°E

Witness: Gary Arrand

I hereby certify the above described corner monument and/or accessories was established as described on May 3, 1985.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>9-18-85</u>
Date Filed ^{★GPC-79922} <u>9-23-85</u>
By <u>G. LANGRISH</u> DEPUTY
File No. <u>65-85 R</u>