


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-07

History of original corner establishment:

This is not an original G.L.O. corner.



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

T5S R35E

Corner set by subdivision of section. (Intersection)

C 1/4 S 29

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 8" above ground. Set steel fence post 4.0 ft. west of corner.

RLS 1844
1984

New BT's:

A 6" L. Pine bears N48.5°E, 30.6 ft., blazed and scribed: C1/4 S29 BT.

A 6" P. Pine bears N18.5°W, 41.0 ft., blazed and scribed: C1/4 S29 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found 38 ft. north of east-west fence. Take road 5155-072 to fence, walk north and west along fence to corner.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 8, 1984.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received 1-23-85
★ GPO-798-276
Date Filed 2-5-85
By G. LANGLITZ, DEPUTY
File No. 17-85 R