


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-2

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Corner falls in small opening near a down tree.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked:

Set pipe 18" in the ground to bedrock and mound of stone around to cap.

From which, by magnetic declination of N20°E:

A 14" fir bears N42°E, 60.5 ft. scribed CW 1/16 S6 BT.

An 11" tamarac bears S43°W, 45.4 ft. scribed CW 1/16 S6 BT.

Placed 54-3s and brass washers stamped PLS 1051 on BTs.

Painted blazes red and 6" red band around. Placed 54-2

and 54-4 on steel fence post 5' East and 54-2 and 54-9 on

steel fence post 5' South of corner.

T6SR38E
W1/16
C ——— C
S6
OR PLS 1051
1979

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Robert S. Stevens
Jerry Rous

September 21, 1979

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon..... I hereby certify that the within instrument was filed in this office

for record on the 6th day of December..... 1979

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY
SURVEYOR

Date Received 798-276

Date Filed _____

By _____

File No. 756-84R