


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
None.



See Survey 052-1494
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2 1/2" X 30" aluminum pipe with a 2 1/2" aluminum cap, 26" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 to steel fence post, set 3.0 feet West of monument.

New bearing trees established:

- A 5" douglas fir bears N 89 1/2°W - 6.8 feet, scribed: "X BT".
- A 12" douglas fir bears N 4°E - 55.6 feet, scribed: C1/4S18BT.
- A 12" douglas fir bears N 32°E - 63.9 feet, scribed: C1/4S18BT.
- A 9" douglas fir bears N 80 1/2°E - 53.0 feet, scribed: C1/4S18BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 3, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 12-31-94

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office

for record on the..... day of.....

..... by.....
(COUNTY OFFICIAL) SURVEYOR (DEPUTY)

UNION COUNTY
SURVEYOR
(DEPUTY)

Date Received 11/3/94

Date Filed 11/14/94

By Gregory T. Black

File No 150-1994R