


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

P-2

History of original corner establishment:
None.



See Survey 052-1994
Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At postion established by survey:

Set a 2½" X 30" aluminum pipe with a 2½" aluminum cap, 28" in ground and surrounded with a mound of earth and stone.

Attached sign 54-9 & 54-2 to steel fence post, set 3.8 feet West of monument.

Set a steel fence post 3.3 feet South of monument.

New bearing trees established:

A 31" ponderosa pine bears S 44° W -118.7 feet, scribed: C-W1/16S19BT.

A 37" ponderosa pine bears S 79° E -227.6 feet, scribed: C-W1/16S19BT.

New bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each bearing tree.

I hereby certify that the above corner monument was properly monumented to U.S.F.S standards by me on December 29, 1993.

Compass declination 18° East.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 12-31-94

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of..... 19.....

(COUNTY OFFICIAL)

UNION COUNTY	
SURVEYOR	
Date Received	<i>11/3/94</i>
Date Filed	<i>11/14/94</i>
By	<i>Guy T. Blain</i>
File No.	<i>160-1994R</i>

(DEPUTY)